- Wear-resistant, adapt to different working conditions
- Acid and alkali resistance, high porosity, good gas permeability, high dust collection efficiency

- Anti-static, adapt to different working conditions
- Conductive fiber and stainless steel conductive material ensure better antistatic performance



- Adapt to different working conditions
- Suitable for temperatures below 125℃, better resistance to organic solvents, oxidants, inorganic and organic acids

- High temperature resistance, high strength, acid and alkali corrosion resistance, wear resistance, folding resistance, easy cleaning, water and oil proof, anti-static
- Adapts to different temperature zones
- Low price and wide application

- Significant temperature resistance
- Good chemical resistance, adapt to different working conditions
- Low backflush pressure, high elastic de-filtering efficiency

- Withstand high temperature, suitable for high temperature of flue gas
- Suitable for collection by electric dust collector

- High strength, chemical resistance
- Suitable for harsh environments, adapts to different temperature zones

- Good heat resistance, good dust stripping, reduced energy consumption
- Anti-corrosion, better acid and alkali resistance
- No water absorption, no moisture absorption
- High filtration efficiency



- Chemical resistant, filter bag chemically stable, not burn-in
- Dust removal efficiency is up to 99.99%
- Low pressure loss and low cost of consumables
- Suitable for flue gas purification, dust removal, dust control and material recovery

Our Factory

Company Advantages

01 21 years of professional experience

02 4 factories

03 Independent research and development team
28 top senior professional researchers

04 2 professional testing centers

05 100% high level ex-factory inspection

06 High quality imported materials

07 2 years quality assurance, repair and replacement

1. □□ □□ □□ □, □□□□ □□, □□ □□ □□, □□ □ □□ □□ □□, PP □□, □□, □□ □□, □□ □□, □□ □□□, □□□ □□□ □□□, □ □ □□.
2. □□□ □□ □□ □□□ □□□ □□□ □□ □ □□ □□□□ 10 □ □□□ □□.
3. API, AWWA, ASME, BS EN, DIN, □□ JIS, TUV, CE, ISO9001, TS, OHSAS, WRAS □□□ □□.
4. □□ □□ □□, R & A; □□ □□; D □□ □□□ □□ □□ □□□ □□□ □ □□□□

Exhibition Photos

Our Certificates

□□ □□ □□
Q1 : □□□ □□□ □□□ □□□ □□□□?
A1 : □□□ □□, □□, □□□ □□□□□.

Q2 : □□ □□?
A2 : □□□ □□ 5-10 □, □□□ □□ 15-90 □ □□ □□□.

Q3 : □□ □□?
A3 : T / T 30 % □□, □□ □ □□ □□□□ □□ □□. □□ □□□□□.

Q4 : □□□ MOQ? □□ □□□ □ □ □□□□?
A4 : □□□ □□ 1pc □□, □□□ □□□ □□□□□. □□□ □□ □□□□□□□.

Q5 : □□□ □□ □□□ □□□□□? □□ □□ □□ □□□ □□□?
A5 : □□□□□, 100 % □□. □□ □□ □□□ □□□□□□.

Q6 : □□ □ □□□ □□ □□ □□□ □□□ □□ □ □ □□□□?
A6 : □□, □□□ □□□ □□ □□□ □□, □□□ □□□□□ □□ □□□ □□□ □□ □□

Q7 : □□□ □□ □ □□□ □ □□?
A7 : 1 □ □□. □□□ □□ □ □□□ □□□□□. □□□ □□□□ □□□□ □□□□□□.