




1. 检查法兰密封面的完整性，确保无裂纹、无缺陷。

2. 检查法兰密封面的平行度，确保平行度在 $\pm 6^\circ$ 以内。



COMPANY EXHIBITION



COMPANY QUALIFICATION



Delivery



Payment



Q1:

A1: 5-10 15-90

Q2:

A2: T/T 30%

Q3:

A3:

Q4:

A4: 1

Q5:

A5: 100% GB ASME API DIN ISO9001;2008

CE TUV

Q6:

A6: 70

Q7:

A7: Valve ISO9001;2008 CE TUV